

FG6890G01 Firmware History

Firmware Version	Changes
v0203	Bugfix: Corrected Receiver position, in SNMP and web interface
v0202	Bugfix: Synchronisation issue, when system starts with a 1s offset to UTC
v0201	First released firmware version